

# valor H3 1000K

Dec 2020


1/2

## New Construction Applications - Clearances

Combustible Mantel—Left Side View

**NOTE**

Use of the optional HeatShift System affects mantel clearances as shown below—see "Appendix D - HeatShift System" in appliance's Installation manual for details.




# valor<sup>®</sup> H3 1000K

Dec 2020  
2/2

## New Construction Applications - Clearances

Combustible Sidewall /  
Mantel Leg—Top View



**Note**

Right Side Clearances are the same